

Index: N06

Corner: W 1/16
S17-S20

LAND CORNER RECORD

Polk F-13

State of Indiana
Hoosier National Forest

Township: 7N

Range: 1E

Section: 20 2nd P.M.

County: MONROE CO.

EXISTING SURVEYS

Original Government Survey				Original Survey Evidence Found			
Year Surveyed:		By:		Date of Search:		By:	
Original Monument:				Monument Found:			
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance
Subsequent Corner Restoration				Evidence of Subsequent Corner Restoration Found			
Where Filed or Recorded: Recorders Office				Year 1906 By: CM Bower			
Book: S.Bk.2 Page: 183 Date: 1871				Searched:			
Monument Set: Not Indicated				Monument Found: Set Stone			
Species	Diameter	Bearing	Distance	Species	Diameter	Bearing	Distance
Beech	8"	S48°E	23-2/3 Lk	Beech	14"	N6°E	24 Lks
				Beech	28"	N86°W	7-1/2 Lks

OTHER EVIDENCE

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
The corner is located on a north facing slope approximately 150' south of an east-northeast ravine, approximately 400' west of a large northwesterly running ravine, 1.5' Northeast of a Wood Cross Tie fence corner with fence remnants running west, south and north	

PERPETUATION RECORD

Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position.													
West 1/16 corner between Section 17 and Section 20; A 0.25'x0.5' sandstone was found 0.3' above grade. This corner was established on a 1891 Legal Survey found in Survey Book 2, page 183-184 by Alexander Spencer. This corner was reestablished as shown a 1906 survey by C.M. Bower, found in Volume 3, page 19. This monument was also used by Steve Archer on a 2004 survey on the Topolpus property in Section 18, being conducted at that same time as this survey.													
Corner Diagram 	Accessories: Describe new BTs & witness objects established to perpetuate existing evidence. 5" Beech N70°W 21.1' 6" Maple S85°E 24.8' 10" White Oak S0°W 12.4' <i>Referenced on BRG survey recorded as InstNo.2005011737.</i> <i>Accepted by the Monroe County Surveyor Review Board on August 6, 2019.</i>												
<table border="1"> <tr> <td>Corner Recordation:</td> <td></td> <td>Certificate Prepared:</td> <td></td> </tr> <tr> <td>Filed and Recorded in County records:</td> <td></td> <td>Date:</td> <td></td> </tr> <tr> <td>Book:</td> <td></td> <td>Page:</td> <td></td> </tr> </table>		Corner Recordation:		Certificate Prepared:		Filed and Recorded in County records:		Date:		Book:		Page:	
Corner Recordation:		Certificate Prepared:											
Filed and Recorded in County records:		Date:											
Book:		Page:											
<table border="1"> <tr> <td>Geodetic Coordinates:</td> <td>Lat./N.</td> <td></td> <td>Long./E.</td> <td></td> </tr> <tr> <td>Section: 20</td> <td>Edited By:</td> <td>BTR</td> <td>Date Created:</td> <td>10/2004</td> </tr> </table>		Geodetic Coordinates:	Lat./N.		Long./E.		Section: 20	Edited By:	BTR	Date Created:	10/2004		
Geodetic Coordinates:	Lat./N.		Long./E.										
Section: 20	Edited By:	BTR	Date Created:	10/2004									

Index: N-6	Corner: W 1/16	LAND CORNER RECORD		State of Indiana Hoosier National Forest	
Twnshp: 7N	Range: 1E	Section: 17/20	2 nd P.M.	County	Monroe
EXISTING SURVEYS					
Original Government Survey			Original Survey Evidence Found		
Year Surveyed:	By:		Date of Search:	By:	
Original Monument:			Monument Found:		
Species	Diameter	Bearing	Distance	Species	Diameter
Subsequent Corner Restoration			Evidence of Subsequent Corner Restoration Found		
Where Filed or Recorded:	Monroe County Surveyors Office		Year Searched:	8/24/04	By: B. Stone
Book: 3	Page: 19	Date: 4/13/1906	Monument Found	3" x 7" stone standing 3" above the ground. Painted red by Bledsoe, Tapp & Riggert, Inc. With small rock cairn.	
Monument Set:	Not stated				
Species	Diameter	Bearing	Distance	Species	Dia.
Beech	14"	N 03°E	24 Lks.	Beech w/old fence	32"
Beech	28"	N 86°W	8.5 Lks.		

OTHER EVIDENCE

Describe corner loc. relative to nearby features & dir. to corner location; note fences, roads, etc.	Sketch of Monument
The stone is located on a north slope in an open forest approximately midslope. A north-south old barbwire fence passes 3 feet west of the stone. A 6"x 7" squared old wooden fence post in the north-south fence line and with fence to the west is leaning badly to the west S 66°W 2.0 feet. An aluminum survey marker post stands at the west side of the stone. The head of a southeast to northwest drainage is approximately 35 feet east.	

PERPETUATION RECORD

Monument: Describe new monument set or work done to perpetuate/preserve the existing monument/position.

	
--	--

Corner Diagram	Accessories: Describe new BTs & witness objects established to perpetuate existing evidence.			
	These bearing trees are blazed, scribed, painted and have red bands but not tags:			
	Maple 7" S 81°E 24.6 Ft.	W. Oak 9" S 02°E 12.2 Ft.	Beech 5" N 69°W 21.0Ft.	
	Corner Recordation:		Certificate Prepared:	
	Filed and Recorded in County records:		Date:	
	Book:		Page:	
Section:	20	Geodetic Coordinates:	Lat./N.	Long./E.
	Edited By: Robert J. Stone	Date Created:	8/30/04	